


RIP-24 mod.01 Wiring Diagram



WARNING

In order to avoid an electrical shock

1. Connect the protection ground to XT1/5 contact and the LINE terminal to XT1/4 contact
2. ALWAYS DO SHUT OFF 220 V and REMOVE F1 FUSE before installing or replacing the backup batteries

How to Turn the Power Supply On

1. Connect the batteries as shown in the schematic using the wire provided
2. Insert the F1 fuse provided
3. Turn on mains power 220 V

How to Turn the Power Supply Off

1. Turn off mains power 220 V
2. Remove the F1 fuse
3. Disconnect X1 and X2 leads from the batteries